


PLM

koleno
přes přepážku



TYP	ØD1	ØD2	ØP	T	L	E	A	B1	B2	J	H1	H2	PRŮTOK (6-ti hran)
PLM04	4	4	11	M12× P1.0	32.4	18.7	9.0	15	15	4.0	14	14	3.0
PLM06	6	6	13	M14× P1.0	36.2	20.4	11.0	15	15	4.0	17	17	4.5
PLM08	8	8	14.4	M16× P1.0	40.3	23.1	11.5	18	18	5.0	19	19	6.0
PLM10	10	10	18.4	M20× P1.0	42.3	23.7	12.0	22	22	5.0	24	24	7.0
PLM12	12	12	21	M22× P1.0	48.1	27.7	15.0	22	22	5.0	26	26	10.0